



**STRATEGIC VISIONARY SOLUTIONS®**  
"Providing Solutions to Your Challenges"

**FOUNTAIN OFFSHORE  
BOAT RESTORATION**

**NANO-CLEAR® INDUSTRIAL COATING FOR THAT'S MINOR CUSTOMS RESTORATION**



**That's Minor Customs**  
Clinton Township, Michigan

**Industrial Customer:**  
That's Minor Customs  
Clinton Township, Michigan  
POC: Frank Maiorano

**Project:**  
Restoration of a Fountain Offshore boat using Nano-Clear® Industrial (NCI) for increased UV protection and reduced maintenance.

**Project Location:**  
Clinton Township, Michigan

**Applicator:**  
That's Minor Customs  
Clinton Township, Michigan  
POC: Frank Maiorano

**Coating Formulation:**  
Nano-Clear® Industrial (NCI) coating

**Application System:**  
Commercial (HVLP) spray gun

**Date:**  
Application: May 2017  
90°F sunny, hot, humid



**Before and After Restoration of a Fountain Offshore Boat using NCI**

**PROJECT OVERVIEW:**  
That's Minor Customs received a Fountain offshore boat with sun damaged paint, hull staining from algae and microbial bacteria resulting in an overall degraded external condition. That's Minor Customs was contracted to restore the exterior of the boat to a like-new condition. The boat was prepared per standard practices, removing zebra mussels, algae staining, and other organic materials, fixing cosmetic flaws, in preparation for touchup paint and a final NCI coating. The protocol for NCI coating was followed for this project.

**COATING FORMULATION:**  
**NCI** – a crystal clear, aliphatic, moisture cured, one component polyurethane/polyuria hybrid formulation with extreme cross-link density for UV, CHEMICAL AND ABRASION RESISTANCE.  
**NCI** is formulated to penetrate and fortify existing paint systems (newly painted or highly oxidized), not replace them.  
**Applications:** Heavy equipment, ships, external structures, fleet equipment, facilities, fences (metal and wood), above ground storage tanks, equipment, bridge rails and signs that have degraded paint/coatings from UV, chemical and abrasion forces.

**RESULTS:**  
The exterior of the boat was fully restored with a protective NCI coating that provides it with over 10 years of UV and corrosion protection.